Exhibit AC

Quote to clean thinset off the brick porch with muratic acid. According to BB Masonry, this has an 80% chance of succeeding in repair damage Floors Outlet did by smearing and drizzling thinset on the porch.

	Guaranteed to make it v Kymbiktrown12@ DESCI		For Edwin Type project or service use Mail Merge (under Information from a dat	Hlexanc description and po	
Remo	shing St Ving Conc	tep rete	HOURS	RATE	AMOUNT \$ 800
Retaining Walls Service Walls					TOTAL
Service Walls		= 4			TOTAL
Service Walls		Ŧ			TOTAL
Service Walls Pavers Rowlock per Ft	X\$	=\$ =\$ =\$			TOTAL

All material is guaranteed to be as specified, and the above work was performed in accordance with the drawings and specifications provided for the above work, and were completed in a substantial workman like manner for the agreed sum of ______ Price includes all materials, and labor

Make checks payable to: B and B Masonry

Thanks for your business, Kenyana & Charles Brown. Owner & Operator